

## BUILDING SAFETY CERTIFICATE

No. 39

Dated.....9/05/2025

It is certified that the existing building Harvard International School(name of the building or premises) at Vill. Bhatoli, P.O. MandPandher, Teh. Dasuya, Distt. Hoshiarpur(address) is having block(s) / Floor(s) as per details below:-

Detail of Block (s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	02	NA	NA	NA	NA	NA

The building is owned/occupied by Harvard International school, Vill. Bhatoli, P.O. MandPandher, Teh. Dasuya, Distt. Hoshiarpur (name of the Institution) have complied with the and verified by the officers concerned of PWD (B+R) Sub Division No. 2 Hoshiarpur(Name of Department / Govt.) on 30.04.2025 (date of inspection) in the presence of Smt. Kanchan Sharma (Chairperson), Vill. Bhatoli, P.O. MandPandher, Teh. Dasuya, Distt. Hoshiarpur (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 01.04.2025 for a period of one year in accordance with rule and subject to compliance of the specific conditions as appended.

1. The water should not be allowed to stand around the building and on the roof.
2. If any part of the building is exposed to any kind of cracks, then the said spot should be vacated immediately and repaired immediately.
3. That the material used in the construction of the building shall be the responsibility of the concerned school.
4. Apart from the attached map, if any additional construction is to be you, then its approval should be taken from the department on priority basis.
5. The inspection fees of Rs. 10,000 has been deposit by the school.

Issued on 09.05.2025 at Hoshiarpur by Sub Divisional Engineer, Constn. Sub Division No. 2 PWD B&R, Hoshiarpur

\* Strike out whichever is not applicable.

Principal  
Harvard International School  
Vill. Bhatoli, P.O. Mand Pandher  
Teh. Dasuya, Distt. Hoshiarpur (Pb.)

Signature with Seal  
Designation: Sub Divisional Engineer

Name & Address of Department/ Office : Sub Divisional Engineer  
Construction Sub Division No.2  
PWD B&R Br;  
Hoshiarpur

President  
MANAGING COMMITTEE  
Harvard International School  
Vill. Bhatoli, P.O. Mand Pandher  
Teh. Dasuya, Distt. Hoshiarpur (Pb.)